

**SAS Superstructure**

Location: 04-SF-80-13.2 / 13.9

Client Name: CalTrans

Run date 21-Nov-14

Time 9:58 PM

**Daily Diary Report by Bid Item**

Contract No.: 04-0120F4

Diary #: 390 Const Calendar Day: 989 Date: 24-May-2012 Thursday

Inspector Name: Altamirano, Victor Title: Transportation Engineer

Inspection Type:

Shift Hours: Break: Over Time:

Federal ID:

Location:

Reviewer: Schmitt, Alex Approved Date: Status: Submit

**04-0120F4  
04-SF-80-13.2/13.9  
Self-Anchored  
Suspension Bridge****Weather****Temperature** 7 AM 50 - 60 12 PM 50 - 60 4PM 50 - 60**Precipitation** **Condition**Working Day ☒ If no, explain:**Diary:**

Dispute

**Work description.**

Inspector: Victor Altamirano (8 hours reg. and 4 hours OT)

Date: 052412

Weather: 60 deg. / Sunny

**Field Work –**

I verified the rotation offset after workers tensioned the cable bands. I started at PP50 and worked my way down the span to PP 70. Note that at panel point 50 and 52 the cable bands were about 9mm from the centerline mark. All others were within tolerance.

Office work: Worked on diaries.

